



HOW DO I RECHARGE AN IGET MOON 5000?

[Infographic]

Prepare four essentials

Essential tools are required for the IGET Moon recharge process:

- An IGET Moon
- A micro-USB cable
- A socket
- A small flathead screwdriver, for instance, is a sharp object.

Step:



The charging cable to the back

- The IGET Moon K5000 lacks a charging cable, in contrast to the rechargeable vape IGET offers. You'll need to remove one of your charging cables to make a new one.
- Use scissors to carefully untangle the wires inside the charging cable. Four wires come in various colors: red, white, and green, with some appearing black.

Step:



For 5 to 10 minutes, charge the Moon IGET's battery.

- When the charger and battery cables are connected correctly, turn on the power by plugging the other end of the charging cable into the socket. It is sufficient to charge it for five to ten minutes.
- The bottom indicator light illuminates when the battery is reconnected with the original wires and is successfully charged.

Step:



Step:



Use a flathead screwdriver to open the IGET Moon Vape

- You cannot access the bottom of the IGET Moon, which is different from other vapes that contain nicotine IGET offers.
- Its sides are smooth and splatter-painted, and a silver piece joins it in the middle. A small flathead screwdriver must be inserted between two sides to create an indent before the IGET Moon can be opened.

Step:



Connect the IGET Moon K5000's battery with the wires.

- To detach its wires, remove the IGET Moon's built-in battery. Then, match the cables' colors to the battery's and connect them. The positive terminal is red to red, and the negative terminal is blue to black.

Step:



Putting the Moon Vap Together

- It's important to note that these are general instructions, and there may be slight variations in the charging process depending on the specific design of the IGET Moon 5000. For precise instructions, it's always recommended to consult the device's user manual or contact the Local Shop for assistance.

Read More:

www.infinityvapesupply.com/collection/iget-moon-5000-puffs

Recharging the IGET Moon 5000 has the potential to be dangerous because of its disposable nature. Wear insulated gloves to avoid electric shock hazards when using protective measures to protect your safety when charging.

Step:1

Prepare four essentials

1. Essential tools are required for the IGET Moon recharge process:
2. An IGET Moon
3. A micro-USB cable
4. A socket
5. A small flathead screwdriver, for instance, is a sharp object.

Step:2

Use a flathead screwdriver to open the IGET Moon Vape

Step:3

The charging cable to the back

1. The IGET Moon K5000 lacks a charging cable, in contrast to the rechargeable vape IGET offers. You'll need to remove one of your charging cables to make a new one.
2. Use scissors to carefully untangle the wires inside the charging cable. Four wires come in various colors: red, white, and green, with some appearing black.

Step:4

Connect the IGET Moon K5000's battery with the wires.

Step:5

For 5 to 10 minutes, charge the Moon IGET's battery.

Step:6

Putting the Moon Vap Together

It's important to note that these are general instructions, and there may be slight variations in the charging process depending on the specific design of the IGET Moon 5000. For precise instructions, it's always recommended to consult the device's user manual or contact the Local Shop for assistance.

For more information about **IGET 5000**, click here www.infinityvapesupply.com/collection/iget-moon-5000-puffs or email us actostrading@gmail.com

Read More: <https://www.quora.com/How-do-I-recharge-an-IG-ET-Moon-5000/answer/Robert-William-489>